





This is an image of a partially submerged barge and the logs that had been spilled over the side of the barge. Note that this image was taken at only 4.8 mph which gave very good level of detail.



This is an image of the same partially submerged barge and the logs but was taken going the opposite direction and at a much higher rate of speed – 35 mph, which gave made for an image that has a much lower level of detail. This is no different than what is seen with the more conventional “2D” sonar as well.