


# Proposed HB Setup



2001 Crestliner – 1850 Sportfish

# Objectives

- Use Ethernet cable to share GPS waypoints/routes and SI/DI imaging between the 798si HD and 998si
- Use transducer Y cable to switch (automatically) between SI transducer and high speed transducer depending on speed (SI transducer mounted higher to avoid impact damage)
- GPS receiver mounted in middle of boat to minimize waypoint error when sharing between 798/998
- Ability to swap bow/console units with full functionality (including SI/DI) when desired

# Questions

- Do I have all the required cables and accessories?